

# **Chapmanville Intermediate School** in Logan County

- A mandated "Recovery Plan" was issued to the low bid contractor when work wasn't completed on time and the contractor still missed the June 2018 completion date.
- Documents show serious quality issues with Insulated Concrete Form's (ICF) walls.
- OSHA inspection revealed multiple violations totaling \$14,000 in initial fines for the general contractor and another \$7,000 for its subcontractor Arch Masonry.
- Contractor committed 50 violations and fined \$12,500 in addition for violation of the WV Jobs Act which requires a certain percentage of workers to be from the local labor market.
- Engineers provided extensive lists of unfinished/substandard work to the contractor as much as 30 days beyond the scheduled completion date.
- Massive punch lists weeks after completion date.
- The Logan County school board had to scramble to reopen a mothballed school since the project was so far behind schedule.

## Click on items below for documentation:

Persinger Recovery Plan	. 2
The OSHA Violations	
Persinger & Associates, Inc	12
Arch Masonry, Inc.	15
WV Jobs Act Violations	17
Terradon Site Review	19
Punch Lists	
Harper Engineering Punch List	27
WSA Exterior Punch List	30
WSA First Floor Punch List	32
WSA Second Floor Punch List	59

# Persinger & Associates

## GENERAL CONTRACTOR

Received

March 9, 2018

MAR 12 2018

Mr. Mark Adkins Logan County Board of Education 250 Holly Avenue Logan, WV 25601

SBA

Re: Chapmanville Intermediate School Request for Plan of Recovery and Recovery Schedule

Dear Mr. Adkins.

I am in receipt of your letter to me dated March 6, 2018 "RE: Chapmanville Intermediate School Directive to Accelerate Work". As requested in that letter, Persinger & Associates, Inc. has created a Recovery Plan that displays several action items to be implemented during a "Recovery Period". A Recovery Schedule has also been created to illustrate, not only the work during the "Recovery Period", but also all work remaining between now and the substantial completion date of June 28, 2018. During the proposed "Recovery Period" Persinger will be working a larger than normal crew and logging an increased number of hours. Also, in the spirit of proving that we are completely dedicated to the success of this project we will pay the hourly overtime premium of any worker from any other Prime Contractor who will work overtime during the "Recovery Period". As an example if a man earns \$50 per hour and he works one hour of overtime and makes \$75 as time and a half, then Persinger would pay \$25 for that hour.

Hard dates have been established as measures of success of the recovery as follows:

- The "Recovery Period" will be from March 7, 2018 to April 11, 2018.
- 2. During the "Recovery Period" Persinger employees will work between 50 and 70 hours per week. Saturdays will be utilized in helping to accumulate these hours.
- 3. During the "Recovery Period" Persinger will staff no less than six men to the project not counting the superintendent. Four men will be framing and 2 will be on clean up duty (all subject to change by superintendent if needed).
- 4. No additional tools or equipment are needed during the "Recovery Period".
- 5. All structural steel at Phase 5 will be complete by March 14<sup>th</sup> and all other steel like stairs and rails by March 28th.
- 6. The metal stud framing in phase 3 will be complete by March 21st.
- 7. All drywall in the entire building will be completed on April 30<sup>th</sup>.

The April 30th drywall completion date falls outside of the "Recovery Period", but should be on track for an April 30th finish on April 11th. We have placed these milestones on the Recovery Schedule attached to this letter.

Thank you,

Courtney Persinger

President

CC: Greg Williamson, Williamson Shriver Architects, Inc. Mike Hall, School Building Authority of WV Scott Raines, School Building Authority of WV



## **CONSTRUCTION FIELD REPORT**

PROJECT:

Chapmanville Intermediate School

LOCATION:

Chapmanville, WV

OWNER:

**Logan County Schools** 

GENERAL TRADES CONTR:

Persinger and Associates 4/11/2018

DATE:

This report is prepared in accordance with the General Conditions of the Contract for Construction and does not imply that the Architect has made exhaustive or continuous on-site inspections on portions of the work to determine that such portions are in proper condition to receive subsequent work. Omission of non-conforming items within this report does not imply that the Architect accepts work not in conformance with the Contract Documents.



## **Items Observed**

## **Exterior - Site**

- Persinger has installed dewatering sumps per the recommendation of the architect's consultant Terradon Corporation.
- The site continues to be wet and muddy although the sumps appear to be working in the areas in which they have been installed. A large portion of the site continues to have deep ruts from movement of equipment and materials.
- Some erosion control measures have been re-installed, primarily inlet protection at storm water catch basins. No silt fence appears to be present on the site.
- Some stone has been delivered to the site and spread to facilitate movement of materials and equipment.

## Interior - Phase 1

- Wall primer painting is ongoing in classroom areas and the corridor.
- Ceiling grid installation is ongoing.
- Gypsum board installation is underway in the east stairwell. Issues regarding the gaps between the walls and steel stair framing have not been resolved.

- A dark substance which may be mold is visible on the gypsum board east wall in room 112. This is the same room where standing water was visible and reported in a previous Construction Field Report. If the substance is mold, then this gypsum board should be removed and replaced.
- Main ductwork appears to be complete or nearly complete.
- Sprinkler piping appears to be complete or nearly complete.
- Extensive HVAC, plumbing, electrical work is ongoing in both rooms 130 and 131.

#### Interior - Phase 2

- Installation of operable partition tracks appear to be complete or nearly complete.
- Main ductwork appears to be complete or nearly complete.
- Sprinkler piping appears to be complete or nearly complete.
- The decorative gypsum board proscenium element at the stage opening is constructed incorrectly and will require remediation.

#### Interior - Phase 3

- Wall insulation and gypsum board installation is underway.
- Electrical, mechanical, and plumbing work are ongoing.
- The door frame at the west stairwell upper landing has been replaced. The workmanship on the concrete patch is very poorly performed.
- The chase housing roof drain rainwater leaders is incorrectly installed in room 204a. The chase extends too far to permit installation of the ADA grab bar and impedes the required ADA clearance requirement. The rainwater conductor will need to be relocated and the chase corrected to maintain these required dimensions.

#### Interior -- Phase 4

- Cold formed metal framing partitions installation is complete or nearly complete.
- Electrical and HVAC work is ongoing
- Voids in the concrete between and around the kitchen windows have not yet been corrected.

### Interior - Phase 5

- Metal stud framing work is commencing this date in this phase.
- Metal stud framing for the main entrance canopy has been installed.

## Building Exterior Façade/Roof

- Brick façade installation is ongoing (approximately 50% complete). Completed areas extend
  from the gym east wall to the stair on the west facade. Brick installation is underway on the
  south wall of the two story academic wing where it is not yet to scaffold height.
- Metal gravel stop has been installed along the entire north face of the building.
- Window installation is complete at phases 2 and 4.
- EPDM roofing is underway at phase 5.
- Flashing reglet at the phase 5 has not been installed correctly in the brick wall, as the placement of the reglet will not facilitate the snap-on cover.
- Installation of wood blocking/nailers at the building parapet continues. This installation resolves inconsistencies between the top of the ICF walls and the top of brick veneer. Work this date was being performed in the Phase 4 Kitchen area.

The building interior is extremely dirty from mud tracked inside and excessively cluttered with waste materials from construction activities to the point that, in Williamson Shriver Architects' opinion, it has to be detrimental to the progress of the work.

Photographic Documentation - Photos of completed work and observations from this visit were taken by the author and have been saved in the appropriate project directory

## Project Meeting #24 - General Items / Meeting Notes

- Official meeting minutes of Owner Construction Progress Meeting #24 are being prepared by Project Coordinator Persinger & Associates.
- Submittals
  - o Persinger requested Operation and Maintenance Manuals, Warranty's etc. be submitted for review as soon as possible as some had not yet been received. These items had been requested for submission by all prime contractors no later than the end of March.
- Open Items:
  - The gymnasium wall pad manufacturer is requesting a vector file for the graphics selected by the Owner. Williamson Shriver Architects is not capable of providing such a file due to software limitations.
  - o The gymnasium floor graphic design is currently out for pricing.
  - o Brick washdown is to be started at the phase I north wall and at the gymnasium at the same time.
- Schedule The recovery schedule was reviewed, as follows:
  - 1. Steel joist and decking in Phase 5 to be completed by March 14<sup>th</sup> Persinger stated that this item was completed per the recovery schedule.
  - 2. Steel work Stair "A" to be completed by March 21<sup>st</sup> Persinger stated that this item was completed per the recovery schedule although there are issues with this installation which must be corrected or remediated.
  - 3. Steel work Stair "B" to be completed by March 21st Installation of this work is now completed, although there are issues with the installation which must be corrected or remediated.
  - 4. Gypsum board in Phase I to be completed by March 21st Persinger stated that this work was complete.
  - 5. Gypsum board in Phase 2 to be completed by March 21st Williamson Shriver Architects' estimate is that this work is approximately 95% complete as of this meeting date.
  - 6. Wall framing to be completed in Phase 3 by March 21st Williamson Shriver Architects estimates that this work is presently approximately 90% complete as of this meeting date.
  - 7. All gypsum board work to be complete by April 30th This work is ongoing.
- Two-Week Look Ahead Persinger presented a two-week look ahead of work proposed to be completed in advance of the next project meeting, including:
  - o Phase I Glass and glazing / brick installation / installation of acoustical ceiling grid;
  - o Phase 2 Install steel support for operable partition track systems / installation of acoustical ceiling grid / cleaning;
  - Phase 3 Glass and glazing installation / brick installation / Interior painting / installation of acoustical ceiling grid;
  - o Phase 4 Finish gypsum board / FRP panel installation / installation of acoustical ceiling grid:
  - o Phase 5 Finish roofing / partition framing / electrical and HVAC rough-in.
- General Discussion Items:
  - Stairwell corrections a meeting is to be held today to discuss correction of the structural steel support and gaps at the walls.
  - The rainwater conductor cleanout in the gymnasium has been relocated. It is unknown why the cleanout was installed approximately 10 feet above the floor elevation or who approved such an installation.

- o Furnishings Delivery Tom Sexton indicated that they are revisiting the possibility of furniture delivery dates after July 9<sup>th</sup>.
- Original STEM Lab Williamson Shriver Architects recommended that a change order proposal should be sought to include a lay-in ceiling within this room due to the type of ductwork installed.
- o Persinger requested an official response to RFIs #35 & 39. Williamson Shriver Architects will respond.
- o The SBA Representative (Mike Hall) expressed several concerns, including:
  - Construction debris cleanup needs to be completed as soon as possible;
  - No smoking is permitted on the construction site. If the SBA catches any
    offenders, they will be removed from the project site immediately;
  - He requested the status of the Recovery Schedule gypsum board installation deadline. Chris Shaw responded that meeting that date "would be tight";
  - Requested Williamson Shriver Architects prepare a list of rejected work/incorrectly installed work and how these items were resolved. Williamson Shriver Architects agreed to assemble such a list:
- o Williamson Shriver Architects issues / comments included the following:
  - Questioned the status of the interior hollow metal frame anchorage. Persinger stated that they accept the solution proposed by the architect and would proceed to install a mock-up at one location;
  - Asked the status of site remediation. Persinger indicated that two sumps had been installed by the proceeding Friday, and four have been installed to date (Bert Bush says three). Pumping continues in these sumps. Persinger has brought in stone to facilitate movement of materials and equipment. Arch Masonry stated that they "cannot move". More stone is forthcoming;
  - Questioned Persinger as to whether the project would be completed by the required Substantial Completion date. Persinger responded that it would be complete.
- o DSO Mechanical issues / comments include the following:
  - They indicated that they need the FRP panels installed in the kitchen to facilitate installation of the exhaust hood;
  - First availability for HVAC unit startup is around the end of April;
  - They have concerns regarding the gas supply line entering the building. Persinger indicated that they would provide a strategy by Friday of this week.
  - Regarding phase 5 HVAC installation, they indicated that they will need a week for rough in.
- o Given Glass and Glazing issues/comments include the following:
  - They are working on the north wall of phases I and 3:
  - Security glazing is expected to be received on site on 4/23;
  - They questioned when they could start on the south elevation of phases 1 and 3. Persinger directed Given to proceed in advance of brick installation,
- SBA Board Representative issues/comments include the following:
  - Concerns regarding out-of-plumb ICF wall installation.
  - Concerns regarding the stairwell installation issues. Persinger responded that this is a layout issue.
  - Sub-Contractor List violations have occurred by Persinger. A1 Drywall was not a permitted sub-contractor and the SBA requires notification of any changes to sub-contractors.
  - Safety concerns -- It was stressed that Persinger needs to make more of an effort to enforce safety procedures.

- o Clerk-of-the-Works issues/comments include the following:
  - Safety He stated his opinion that Persinger is not following the advice of their safety consultant;
  - Mud on the perimeter road is not being cleaned;
  - Questioned the location / order status of several material items including specialty hollow metal framed that were ordered two months ago;
  - Safety railings need to be installed at roof hatch ladders;
  - Questioned the status of the elevator. Persinger responded that the materials are scheduled to be delivered the end of May;
  - Some cast stone window sills are not installed in areas of finished brick.
  - The installation of the door frame at second floor "stair B" is of very poor quality;
  - Concerned about the lack of progress in remediation of the stair issue;
  - Recommended a "running punch list" compiled at both 60 days and 30 days prior to scheduled substantial completion;
  - Questioned why Persinger employees are permitted to leave the site at lunch on payday Fridays.
- Logan County Schools representatives stated that they are very concerned about the poor quality of work and failures in management of the project.
- o Inspectors from the Occupational Safety and Health Administration (OSHA) arrived onsite while the meeting was underway.

Next meeting will be held on April 28th at 9 a.m. at the project site.

Gregory A. Williamson AlA

## **Persinger and Associates**

## Construction Issues

## April 23, 2018

This is a general summary of construction issues encountered on this project as of the above date. Omission of non-conforming items within this list does not imply that the Architect accepts work not in conformance with the Contract Documents.

- 1. Voids discovered in the concrete core of Insulated Concrete Form (ICF) construction in several areas
  - a. Persinger directed to remove foam and fill voids with grout.
- 2. Problem at General Office 101: The Architect discovered that two ICF walls were incorrectly located, the steel column was incorrectly located and installed and then field modified by Persinger without authorization, Integrated Frame Assembly (IFA) frames were fabricated incorrectly, Arch Masonry installed IFA frames incorrectly.
  - a. Persinger was directed by the Architect to rebuild this building corner per the Contract Documents.
  - b. Persinger removed IFA frames, ICF construction, and corrected layout geometry.
  - c. Persinger relocated the anchor bolts and replaced the steel column.
  - d. Persinger ordered and installed new IFA frames.
  - e. Persinger rebuilt the associated ICF construction.
  - f. Persinger has been directed by the Architect to correct steel support at top of new column.
- 3. Brick Haunch at Room 103 was installed on the wrong side of wall.
  - a. The Architect developed an acceptable remedial design and issued sketch sk-s10 to correct.
  - b. Persinger installed steel support per sk-s10.
- 4. Brick Haunch between Music 142 and Corridor CO2 concrete was incorrectly constructed due to honeycombing.
  - a. Haunch was rejected by the Architect/structural engineer and Persinger was directed by the Architect to provide a remedy.
  - b. Persinger provided a detail for correction designed by a professional engineer for review.
  - c. Detail was approved by the Architect/structural engineer and remedy was installed.
- 5. ICF wall above Man Trap 101b was incorrectly located and installed.
  - a. The Architect developed an acceptable remedial design and issued sketch sk-s14 to make the in-place work acceptable.
- 6. The Architect discovered that most Interior hollow metal door frames were incorrectly installed. The specified floor anchorage was omitted by Persinger.

- a. Persinger provided a detail for correction for review.
- b. The Architect approved Persinger's proposed remediation detail for one prototype location (at Room 133 on Door A135) for installation and review.
- 7. Several IFA frames were installed in the wrong locations.
  - a. Persinger removed IFA frames and reinstalled them in the correct locations.
  - b. Voids in the concrete were discovered along the perimeter of these repairs which were filled with grout by Persinger.
- 8. Several ICF walls were discovered to be out-of-plumb or out-of-tolerance in some way.
  - a. These out-of-plumb/out of tolerance walls were determined by the Architect / structural engineer to not be a structural concern.
  - b. Persinger was directed by the Architect to rasp or shim as required to provide an acceptable installation.
  - c. The Architect worked with Given Glass to develop acceptable window frame installation positioning responding to incorrectly installed ICF walls.
- 9. Brick anchors were discovered by the Architect to be incorrectly installed.
  - a. Persinger was directed by the Architect to remove all brick with incorrect anchorage.
  - b. Persinger rebuilt brick construction with correct anchors.
- 10. Several site catch basins were damaged by construction equipment.
  - a. Persinger was directed by the Architect to replace all damaged catch basins and inspect all associated underground piping for damage.
- 11. It was noted that the Erosion and Sediment.Control Plan/Permit had not been followed.
  - a. Persinger was directed by the Architect to comply with the requirements of the Plan included in the contract documents and the Permit issued by WVDEP.
- 12. Adequate dewatering of the site was not accomplished as specified by the Construction Documents.
  - a. Persinger was directed by the Architect and consultant Terradon to dewater the site.
  - b. Terradon requested by the Architect to advise Persinger in site remediation.
  - c. Persinger was directed by the Architect/Terradon to install stone sumps with pumps to remove water.
  - d. Persinger was directed by the Architect to verify that underground utilities have not been compromised and to repair or replace as required.
  - e. Terradon will provide direction to Persinger for correction of soil conditions.
- 13. Persinger installed brickwork on north side of kitchen and mechanical rooms with incorrect color pattern.
  - a. The Architect permitted incorrect pattern to remain.
- 14. Persinger installed ICF stairwell walls for Stairs 'A' and 'B' out of square and incorrect dimension.
  - a. Steel erector (Persinger's subcontractor) installed stair framing square leaving varying gaps between the steel stair framing and the face of the ICF walls.

- a. Persinger provided a detail for correction for review.
- b. The Architect approved Persinger's proposed remediation detail for one prototype location (at Room 133 on Door A135) for installation and review.
- 7. Several IFA frames were installed in the wrong locations.

435.00

- a. Persinger removed IFA frames and reinstalled them in the correct locations.
- b. Voids in the concrete were discovered along the perimeter of these repairs which were filled with grout by Persinger.
- 8. Several ICF walls were discovered to be out-of-plumb or out-of-tolerance in some way.
  - a. These out-of-plumb/out of tolerance walls were determined by the Architect / structural engineer to not be a structural concern.
  - b. Persinger was directed by the Architect to rasp or shim as required to provide an acceptable installation.
  - c. The Architect worked with Given Glass to develop acceptable window frame installation positioning responding to incorrectly installed ICF walls.
- 9. Brick anchors were discovered by the Architect to be incorrectly installed.
  - a. Persinger was directed by the Architect to remove all brick with incorrect anchorage.
  - b. Persinger rebuilt brick construction with correct anchors.
- 10. Several site catch basins were damaged by construction equipment.
  - a. Persinger was directed by the Architect to replace all damaged catch basins and inspect all associated underground piping for damage.
- 11. It was noted that the Erosion and Sediment Control Plan/Permit had not been followed.
  - a. Persinger was directed by the Architect to comply with the requirements of the Plan included in the contract documents and the Permit issued by WVDEP.
- 12. Adequate dewatering of the site was not accomplished as specified by the Construction Documents.
  - a. Persinger was directed by the Architect and consultant Terradon to dewater the site.
  - b. Terradon requested by the Architect to advise Persinger in site remediation.
  - c. Persinger was directed by the Architect/Terradon to install stone sumps with pumps to remove water.
  - d. Persinger was directed by the Architect to verify that underground utilities have not been compromised and to repair or replace as required.
  - e. Terradon will provide direction to Persinger for correction of soil conditions.
- 13. Persinger installed brickwork on north side of kitchen and mechanical rooms with incorrect color pattern.
  - a. The Architect permitted incorrect pattern to remain.
- 14. Persinger installed ICF stairwell walls for Stairs 'A' and 'B' out of square and incorrect dimension.
  - a. Steel erector (Persinger's subcontractor) installed stair framing square leaving varying gaps between the steel stair framing and the face of the ICF walls.

- b. The Architect has requested a repair remedial design be prepared by Persinger.
- c. The Architect and clerk of the works have attempted to assist with development of a remedial design.
- d. This item remains unresolved.
- 15. ICF construction was not installed per the Drawings to receive mounting brackets for sunshades.
  - a. Persinger was directed by the Architect to redesign sunshade mounting brackets.
- 16. ICF wall construction topped out at a different elevation than the brickwork.
  - a. Persinger was directed by the Architect to provide a remedial design.
  - b. The Architect has worked with Par Roofing to design an acceptable remedy.
- 17. The Architect discovered that keyed concrete joints were not installed as required in certain concrete slab installations.
  - a. Persinger was directed by the Architect to use keyed construction joints from this point forward.
- 18. It was discovered that Persinger was installing the Wal-mat acoustical insulation system with incorrect fastener spacing.
  - a. WSA directed Persinger to install fasteners at 2'-0" on center instead of 4'0" on center.
  - a. The geometry of the surround is incorrect.
  - b. This item remains unresolved.
  - a. Par Roofing has offered an alternative detail for this flashing.
  - b. The Architect has conditionally accepted the alternative detail pending review of the results.

**OSHA** 

English | Spanish

Find it in OSHA

Q

A TO Z INDEX

ABOUT OSHA ♥ WORKERS ♥ EMPLOYERS ♥ REGULATIONS ♥ ENFORCEMENT ♥ TOPICS ♥ NEWS & PUBLICATIONS ♥ DATA ♥ TRAINING ♥

## **Inspection Detail**

## Case Status: PENDING ABATEMENT OF VIOLATIONS, PENDING PENALTY PAYMENT

**Note:** The following inspection has not been indicated as closed. Please be aware that the information shown may change, e.g. violations may be added or deleted. For open cases, in which a citation has been issued, the citation information may not be available for 5 days following receipt by the employer for Federal inspections or for 30 days following receipt by the employer for State inspections.

Inspection: 1309636.015 - Persinger & Associates, Inc.

**Inspection Information - Office: Charleston** 

Nr: 1309636,015

Report ID: 0316400

Open Date: 04/11/2018

Persinger & Associates, Inc.

97 Tiger Circle

Union Status: NonUnion

Chapmanville, WV 25508

SIC:

NAICS: 236220/Commercial and Institutional Building Construction

Mailing: P.O. Box 511, Charleston, WV 25322

**Inspection Type:** 

Complaint

Scope:

Partial

Advanced Notice:

N

Ownership:

Safety/Health:

Private

Safety

Close Conference:

04/18/2018

Close Case:

Related Activity:

Type

ΙD

Safety

Health

Complaint

1325712

Yes

## Case Status: PENDING ABATEMENT OF VIOLATIONS, PENDING PENALTY PAYMENT

	V	iolation	Summary	/		
	Serious	Willful	Repeat	Other	Unclass	Total
Initial Violations	5			1		6
Current Violations	3			1		4
Initial Penalty	\$14,042	\$0	\$0	\$0	\$0	\$14,042
Current Penalty	\$7,000	\$0	\$0	\$0	\$0	\$7,000
FTA Amount	\$0	\$0	\$0	\$0	\$0	\$0

					Violat	ion Items					
	#	ID	Туре	Standard	Issuance	Abate	Curr\$	Init\$	Fta\$	Contest	LastEvent
	1.	01001A	Serious	19100134 C01	07/26/2018	08/21/2018	\$1,900	\$2,217	\$0		I - Informal Settlement
	2.	01001B	Serious	19100134 E01	07/26/2018	08/21/2018	\$0	\$0	\$0		I - Informal Settlement
Deleted	3.	01001C	Serious	19100134 F02	07/26/2018	08/21/2018	\$0	\$0	\$0		I - Informal Settlement
	4.	01001D	Serious	19100134 K03	07/26/2018	08/14/2018	\$0	\$0	\$0		I - Informal Settlement
	5.	01001E	Serious	19100134 K06	07/26/2018	08/14/2018	\$0	\$0	\$0		I - Informal Settlement
	6.	01002	Serious	19100178 L01 I	07/26/2018		\$2,550	\$2,956	\$0		I - Informal Settlement
Deleted	7.	01003A	Serious	19101200 G08	07/26/2018	08/14/2018	\$0	\$2,217	\$0		I - Informal Settlement
Deleted	8.	01003B	Serious	19101200 H01	07/26/2018	08/21/2018	\$0	\$0	\$0		I - Informal Settlement
	9.	01004A	Serious	19260150 C01 I	07/26/2018		\$2,550	\$2,956	\$0		I - Informal Settlement
	10.	01004B	Serious	19260150 C01 VIII	07/26/2018	08/07/2018	\$0	\$0	\$0		I - Informal Settlement
Deleted	11.	01005A	Serious	19260501 B01	07/26/2018	08/07/2018	\$0	\$3,696	\$0		I - Informal Settlement
Deleted	12.	01005B	Serious	19260501 B04 I	07/26/2018	08/07/2018	\$0	\$0	\$0		I - Informal Settlement
Deleted	13.	01005C	Serious	19260501 B14	07/26/2018	08/07/2018	\$0	\$0	\$0		I - Informal Settlement
	14.	02001	Other	19261053 B16	07/26/2018	08/07/2018	\$0	\$0	\$0		I - Informal Settlement

Occupational Safety and Health Administration 200 Constitution Ave NW Washington, DC 20210 \$\scrtes 800-321-6742 (OSHA) TTY www.OSHA.gov

#### **FEDERAL GOVERNMENT**

White House
Disaster Recovery Assistance
USA.gov
No Fear Act Data
U.S. Office of Special Counsel

#### **OCCUPATIONAL SAFETY AND HEALTH**

Frequently Asked Questions
A - Z Index
Freedom of Information Act
Read the OSHA Newsletter
Subscribe to the OSHA Newsletter
OSHA Publications
Office of Inspector General

## **ABOUT THE SITE**

Freedom of Information Act Privacy & Security Statement Disclaimers Important Website Notices Plug-Ins Used by DOL Accessibility Statement

OSHA

English | Spanish

Find it in OSHA

Q

A TO Z INDEX

ABOUT OSHA WORKERS EMPLOYERS REGULATIONS ENFORCEMENT TOPICS RESULTIONS DATA TRAINING

## **Inspection Detail**

## **Case Status: PENDING PENALTY PAYMENT**

**Note:** The following inspection has not been indicated as closed. Please be aware that the information shown may change, e.g. violations may be added or deleted. For open cases, in which a citation has been issued, the citation information may not be available for 5 days following receipt by the employer for Federal inspections or for 30 days following receipt by the employer for State inspections.

Inspection: 1309646.015 - Arch Masonry, Inc.

**Inspection Information - Office: Charleston** 

Nr: 1309646.015

Report ID: 0316400

Open Date: 04/12/2018

Arch Masonry, Inc.

97 Tiger Circle

Union Status: NonUnion

Chapmanville, WV 25508 SIC:

NAICS: 238140/Masonry Contractors

Mailing: 500 Dargan Street, Pittsburgh, PA 15224

**Inspection Type:** 

**Prog Related** 

Scope:

Partial

Advanced Notice:

N

Ownership:

Private

Safety/Health: Safety

Close Conference:

04/12/2018

Close Case:

**Case Status: PENDING PENALTY PAYMENT** 

	Vi	iolation	Summary	1		
	Serious	Willful	Repeat	Other	Unclass	Total
Initial Violations	1					1
Current Violations				1		1
Initial Penalty	\$7,760	\$0	\$0	\$0	\$0	\$7,760
Current Penalty	\$0	\$0	\$0	\$4,656	\$0	\$4,656
FTA Amount	\$0	\$0	\$0	\$0	\$0	\$0

				V	iolation	Items				
#	ID	Туре	Standard	Issuance	Abate	Curr\$	Init\$	Fta\$	Contest	LastEvent
1.	01001	Other	19100178 L01 I	07/25/2018		\$4,656	\$7,760	\$0		I - Informal Settlement

Occupational Safety and Health Administration 200 Constitution Ave NW Washington, DC 20210 \$\infty\$ 800-321-6742 (OSHA) TTY www.OSHA.gov

## **FEDERAL GOVERNMENT**

White House
Disaster Recovery Assistance
USA.gov
No Fear Act Data
U.S. Office of Special Counsel

## **OCCUPATIONAL SAFETY AND HEALTH**

Frequently Asked Questions
A - Z Index
Freedom of Information Act
Read the OSHA Newsletter
Subscribe to the OSHA Newsletter
OSHA Publications
Office of Inspector General

#### **ABOUT THE SITE**

Freedom of Information Act Privacy & Security Statement Disclaimers Important Website Notices Plug-Ins Used by DOL Accessibility Statement

## WEST VIRGINIA DIVISION OF LABOR

1900 Kanawha Boulevard East - State Capitol Complex – Building 3, Room 200 - Charleston, WV 25305 Telephone: (304) 558-7890 labor.wv.gov Fax: (304) 558-3797



May 24, 2018

Ever Castillo, Owner Ever Castillo 12005 Bluhill Road Silver Spring, MD 20902

Re: West Virginia Jobs Act – Notice of Penalties

Mr. Castillo:

The Logan County Board of Education, in accordance with its responsibilities under W. Va. Code \$21-1C-5(b), has submitted certified payroll records to the Division of Labor ("Division") for work performed by your company on the Chapmanville Intermediate School Project.

The Jobs Act has specific requirements for hiring employees from the local labor market on any public improvement project that is funded entirely from state funds. The project falls under Jobs Act requirements.

The Division has carefully reviewed your certified payroll records from the week ending February 16, 2018 through March 2, 2018 to determine the extent or lack of your company's compliance with the Jobs Act local labor market requirements.

Based on our review of your records, we have identified fifteen (15) work days in which your company did not comply with its obligation to employ individuals from the local labor market. For each day that your company had employees working on the project without employing at least 75% of employees from the local labor market, the Division determined there were 50 violations of the Jobs Act, totaled on a work week basis, as follows:

• For the week ending 02/16/2018: a total of 15 violations

• For the week ending 02/23/2018: a total of 15 violations

• For the week ending 03/02/2018: a total of 20 violations

Pursuant to W. Va. Code §§21-1C-5(e) and 21-1C-6, the Division is authorized to collect civil penalties of \$250.00 per each employee less than the required threshold of 75% per day of violation of the Jobs Act requirements. Based on the number of violations noted above, the Division has

Ever Castillo, Owner May 24, 2018 Page Two

determined that the civil penalties total \$12,500.00. This amount is due and payable to the West Virginia Division of Labor within **ten** (10) **days** of receipt of this letter.

Should you wish to contest the matters set forth in this letter, you must notify me in writing within **ten (10) days** of its receipt, setting forth your objections. I will thereafter arrange a hearing to be conducted pursuant to the procedures set forth in the Contested Cases article of the State Administrative Procedures Act, W. Va. Code §29A-5-1, *et seq*. In accordance with W. Va. Code §29A-5-1(a), you will be provided with a written notice of the hearing date, time, and place at least 10 days prior to the hearing.

If you have any questions, please do not hesitate to contact Wage and Hour Director William F. Jordan at (304)558-7890 or via email to <u>JobsAct@wv.gov</u>.

Sincerely,

Mitchell E. Woodrum

Withele Woodum

Commissioner

cc: David L. Roach, Executive Director - School Building Authority (SBA)
Dana Womack, Assistant Director of School Planning and Construction - SBA
Persinger & Associates, Inc. - General Contractor

Mark Adkins - Logan County Board of Education



P.O. Box 519 Nitro, WV 25143 Tel: 304-755-8291 Fax: 304-755-2636 www.terradon.com P.O. Box 1635 Lewisburg, WV 24901 Tel: 304-645-4636 Fax: 304-645-7614

August 10, 2018

Mr. Ted Shriver Williamson Shriver Architects 717 Bigley Ave. Charleston, WV 25302

RE: Civil Site Review – Substantial Completion Site Work for Chapmanville Intermediate School – Chapmanville, West Virginia Terradon Project No. 1601-0452-004

## Dear Ted:

TERRADON Corporation performed a visual site evaluation of work performed to date at the Chapmanville Intermediate School site on August 10th, 2018. Overall the site was fairly dirty with soiled pavements, seeded lawn areas were partially established and erosion observed was minimal. The following bullet points are issues identified through visual observations and are considered deficiencies that should be addressed (this review is not all-inclusive and all work is subject to conform to plans & specifications):

- At the main vehicular entrance to the school complex traffic control signage had not been installed including "Do Not Enter", "One Way", and "Stop" signs.
- All asphaltic seal coating was applied in areas specified on plans but it was very difficult
  to determine how well it was applied due to how dirty the roads were, and this includes
  areas of asphalt overlay and full depth asphalt. All roadways included in the scope of
  work for the project should be thoroughly swept and cleaned before condition of sealcoat
  application can be evaluated.
- New concrete sidewalks were dirty and should be swept and cleaned thoroughly, many areas had black tire mark tracks from vehicles such as bobcats which left marking on surface of pavement.
- Lawn areas of project need to be weeded, rocks and clumps of dirty larger than ½" should be removed, further fine grading should be selectively performed in areas to smooth rough appearance and tire tracks, lawn should be mowed and maintained at a height of 2-3" until 60 days from date of substantial completion, and bare areas should be overseeded and mulched until lawn is fully established. It is also noted that some construction debris still remains in areas of lawn such as brick. It is particularly noted that the bus loop & parent loop island areas needs more attention, additional fine grading at the service area entrance to smooth rough areas and tire ruts, and additional tire rutting on west side of school in lawn area. See pictures 1-6.
- Many landscape plantings appear to be planted too high and have not been properly backfilled with planting mix and compacted properly. It is noted that some shrubs were high and leaning and were very easily pulled out of the ground, and two shrubs were already mostly dead. It is also noted that many trees were leaning (especially in the plaza area) and were not supported and braced. See pictures 7 10.

- All chain link fencing on project lack bottom 1 5/8" steel bottom rail per detail L/C-501 and project specifications.
- Accessible parking signs were installed at the ADA parking spaces adjacent to elementary school & softball field but no passenger loading zone sign was installed at striped van accessible space. All other ADA parking areas of project lack specified signage. See pictures 11 13.
- Elementary & Intermediate School signs have been installed but they still lacked lettering and brick should be thoroughly cleaned prior to lettering installation. It is also noted that a portion of the sign top stone cap was damaged on the Intermediate School sign.
- Bollards have been installed at school service area but they still have not been painted.
- The heavy duty concrete pavement at the service area has been installed but a construction dumpster still needs to be removed and area thoroughly swept and cleaned, including removing all black tire marks from rubber tired construction vehicles.
- The surface of the asphalt pavement at the bus loop generally has a rough appearance and it does not appear to have been rolled tightly enough to completely seal off surface of asphalt, there are areas of large voids in the surface similar to a base course application of asphalt. Measuring along the curbing there are areas where the curb is greater than 6" in height, many areas are 7-8" in height. I also did not notice any asphalt core tests taken and I have not seen any reports of these required core tests or density reports which should have been coordinated with Owner. It is my recommendation to have these core tests and density tests done per project specifications to check for pavement thickness and density to better determine the quality of the asphalt placed on the entire project for areas of full depth pavement. See pictures 14 15.
- There is striping at the bus loop that is not correct. The center lane line leading into the bus loop island has not been placed correctly, it will need to be adjusted to allow a 12-foot wide outbound lane and 18-foot long parking spaces that back out into the loop transition area (currently parking spaces only have 15-17 foot lengths and outbound drive isle is less than 12 feet wide).
- The bus loop asphalt pavement also has multiple "bird baths" or low spots where water is puddling which should be remedied. Procedure for remediation of low spots to be determined based on core & density test results. See pictures 16 19.
- The parent vehicular drop-off loop has one noticeable low spot which sediment has collected at the ADA parking area which should be remediated. See picture 13.
- There are many areas where the new asphalt pavement has been damaged by construction equipment and also one area where there is an unexplained 7" diameter core in pavement left open. The area of the entire project HMA pavement should be walked and any damaged areas fixed. In particular on the north end of the building in the area where there is a portion of full depth pavement in a parking area; the 7" core was noticed along with tire imprints and divots. See pictures 20 23.
- New concrete sidewalk has significant cracking at the following locations which panels should be saw cut out and replaced with new concrete sidewalk: around the Elementary School ADA curb ramp has three cracks and a chipped portion of concrete, at the parent vehicle drop off loop on the Elementary School side there is a cracked panel adjacent to some chain link fence supplies stockpiled, adjacent to the mulched/fenced play area beside the service gate there is a cracked panel, and on the west side of the mulched/fenced play area there is a cracked panel adjacent to the parking island with connecting sidewalk. See pictures 24 26.



- Some sidewalk is awkward and has a hump in the triangular area adjacent to bus loop. We have asked Persinger to look into the as-built conditions to determine if the grading was followed correctly in this area. See picture 15.
- There is a portion of the sidewalk on the west side of the mulched/fenced play area which does not have any contraction joints placed for about 26 feet starting at the 3<sup>rd</sup> parking space on the south side ranging to the 6<sup>th</sup> space. Contraction joints should be saw cut into concrete in this area. Near this area there is a large chipped portion of concrete sidewalk underneath the fence of the play area.
- There is a large gap left between the new sidewalk & fencing installed at the bus loop (along the paved concourse of the softball field) which should be filled with either asphalt, concrete or compacted aggregate. See picture 27.
- It is noted that the main center area of the concrete pedestrian plaza between the two schools (area of flag poles) did not follow the broom finish pattern as shown on sketch sk-st3. Broom pattern is 90 degrees different from direction shown on sketch.
- There are multiple areas where concrete curbing has cracked or has been chipped and damaged and should be repaired, the following locations have been observed: the bus loop island curb has cracks in three (3) locations on the outbound side, there are at least five (5) cracks observed in the curb at the parking island adjacent to the west entrance to the Intermediate School (w/ fire hydrant), and there are numerous chipped areas along the outside radius of the parent vehicular loop (some have already been repaired but the repair has not been rubbed and finished well so I suggest these be re-done).
- There is a 60-foot portion of concrete curbing on the outbound side of the bus loop directly after CB A7 which have no control joints. New control joints should be sawed at least every 10 linear feet.
- There are catch basins in which some storm pipes have not been grouted at the is connection (mostly pvc roof drains). The following catch basins are noted to have at least one un-grouted connection left: CB A0, A1, A2, A4 & A5.
- The paved play area pavement should be cleaned.
- Inlet protection has been prematurely removed at CB B2 & B3 & should be restored until lawn areas have fully established. Area around CB B2 is rough & has eroded & should be fine graded again. CBB3 is completely clogged & should be cleaned out. See picture 28.
- There is a small lawn area that is too abrupt and should be fine graded better. This area is on the north side of the building near the service area and existing fire hydrant. The ground is too high at the corner of the parking area and this area should be cut down and tapered back gradually, then re-seeded. See picture 29.
- The existing fire hydrant on the north end of the building has been protected with black plastic and marker, these should be removed and fire hydrant cleaned. See picture 30.

This concludes my evaluation of the site and if you have any questions or comments please contact me at your earliest convenience.

Sincerely,

Pete Williams, ASLA Project Manager

Petr Williams

Attachments Cc: file





Picture -1: Photo of lawn area not fully established.



Picture – 4: Photo of bus loop island w/ bare areas & requiring mowing.



Picture – 2: Photo of bare & rocky lawn area by entrance of building.



Picture – 5: Photo of tire tracks in lawn area on west side of bldg.



Picture -3: Photo of parent drop-off loop island with bare spots, weeds, and in generally rough condition.



Picture -6: Photo of tire tracks & lawn area in generally rough condition at service area.



Picture – 7: Photo of rocky lawn area not fully established.



Picture -8: Photo of two shrubs which were noticed planted very high and were VERY easily lifted up by school administrators.



Picture – 9: Photo of one dead shrub and another which is nearly dead.



Picture – 10: Photo of a tree at the pedestrian courtyard leaning.



Picture -11: Photo of ADA parking spots across from elementary school which lack a sign at the loading zone.



Picture -12: Photo of ADA parking & loading zone without signage & very dirty pavement.



Picture – 13: Photo of ADA parking space & loading zone at parent drop-off loop lacking signage and with low area.





Picture – 14: Photo of rough wearing course pavement found at bus loop.



Picture – 17: Photo of low spot in pavement.



Picture – 15: Photo of uneven curb height and of abrupt high spot Picture – 18: Photo of low spot & dirty new pavement. in concrete sidewalk.





Picture – 19: Photo of low spots along curbing to CB A7..



Picture – 20: Photo of scrape / divot in new pavement.



Picture – 21: Photo of tire imprint & low spot in pavement.



Picture – 22: Photo of tire imprints & divots in new pavement.



Picture – 23: Photo of 7" dia. core hole in pavement.



Picture – 24: Photo of cracked sidewalk @ ADA ramp.



Picture – 25: Photo of cracked sidewalk @ ADA ramp.



Picture – 26: Photo of chipped concrete sidewalk @ ADA ramp.



Picture – 27: Photo of gap between sidewalk & fencing which should be filled.



Picture – 28: Photo of area around CB B2 which is rough.



Picture -29: Photo of corner of parking space where grade is too abrupt at corner and soil should be excavated & removed.



Picture -30: Photo of fire hydrant which protection can be removed and hydrant cleaned..

52B Street
St. Albans, WV 25177
Office: 304.722.3602 Fax: 304.722.3603

52B Street

St. Albans, WV 25177 Phone: (304) 722-3602 Fax: (304) 722-3603 jason@harperengwv.com

August 21, 2018

Don Beyer Williamson Shriver Architect Inc. 717 Bigley Avenue Charleston, WV 25302

Re: Chapmanville Substantial Completion Walk thru

A representative of Harper Engineering visited the site on Wednesday, August 15, 2018. The following items were noted.

#### General

- Install Panel Directories and install label for all panels and mechanical equipment per specifications.
- Plumb and level all face plates, receptacles, switches, data outlets etc. Repair/replace all faceplates that are damaged. (Ex. Switches Lobby 101)
- Repair all ceiling tile where Sprinkler head escutcheons do not cover hole. (Ex. Guidance 106)
- Adjust all cleanout covers/ floor drains, flush to floor.
- Touch-up all light fixtures that show scuffs scratches or marks.
- Repair /touch-up all damaged wire mold.
- Adjust all tie-wire for light fixture supports to hang plumb. Trim or lace fixture support wire. (ex. Classroom 118)
- Adjust water flow for all drinking fountains so that over splash onto the floor does not occur.
- All electrical device faceplate covers to be ivory.
- Cap exterior cleanouts with solid caps.
- Install outlets to all laptop charging cabinets.
- Provide USB adaptors for laptop charging cabinet fans.
- Dryer vents need to be sealed at ceiling.
- Provide reports for TAB, commissioning and controls.
- Remove and patch all rough-in not used.
- Weather proof all stub-outs for future stem lab addition.

## Exterior

- Remove rust and touch up paint on all exterior HVAC Units.
- After touch up painting install all missing screws on HVAC Units.
- Remove rust from stainless steel flu extension on RTU.
- Condensate drains traps on RTU's need to be plumbed down.
- Roof top condenser boots need to be clamped.
- RTU 1 weather proof cover plate needs installed for blank cut-out.
- RTU 5 is vibrating and needs checked out.
- Clean gravel and debris from RTU frames.
- RTU 3 install barometric hood as required.
- Water heater flu needs to be extended above 2<sup>nd</sup> floor roof.
- Anchor condensing units to concrete pads.
- Photo cell on roof needs to be secured.
- Gas line needs to be painted beside of kitchen.
- Gas line on kitchen roof needs to be strapped.

## Mechanical Room 130

- Touch up finish on floor drain.
- Touch up drywall around horn strobe.
- Rain water vertical needs secured.
- Panels need directories and labels per spec.

## General Office 101

- Fix light switch cover plates.
- Plumb data outlet.

#### Guidance 106

- Tile needs replaced where sprinkler head escutcheons do not cover hole.
- Adjust floor cleanout to be flush with floor.

## **Assistant Principal 102**

• Fixture needs touch-up.

## Lobby C01

Door hold open needs repaired.

## Classroom 112

- Diffuser is bent needs repaired or replaced.
- Speaker is not flush and needs to be adjusted.

## 1st Floor Corridor

- Hand wash fixture is scratched, needs repaired and caulked.
- Horn strobe needs secured.
- Drinking fountains water flow needs adjusted.

## Speech 114

• Repair loose receptacle.

## Toilet 115a

• Exhaust fan not working.

## Classroom 117

• Wire mold is damaged and needs repaired or replaced.

## Classroom 128

• Wire mold is damaged and needs repaired or replaced.

## Custodian 125

• Mop sink fixture is loose and needs to be secured.

## Classroom 118

- Trim or lace fixture support wire.
- Adjust tie wire for fixture supports.

## Food Prep 138

- Drain escutcheons need to be flush with wall.
- Walk-in cooler, and freezer condensation drain needs to be plumbed per drawings.

## Dry Food Storage 138h

• Wall surface around switch needs to be touched-up.

## Dining 140

• Verify height of drinking fountains, adjust water flow.

## Classroom 211

• C02 detector broken, needs replaced.

## 2<sup>nd</sup> Floor Corridor

• Drinking fountains water flow needs adjusted.



## **EXTERIOR PUNCH LIST**

PROJECT: Chapmanville Intermediate School

LOCATION: Chapmanville, WV
OWNER: Logan County Schools
GENERAL TRADES CONTR: Persinger and Associates

DATE: 8/10/2018

## **Items Observed**

## General:

- I. Clean mortar from brick masonry construction.
- 2. Remove and patch all screws and strings from masonry.
- 3. Clean acid stain from brick.
- 4. Caulk all canopy soffits at brick.
- 5. Caulk all door frames.
- 6. Install all downspout boots.
- 7. Replace wall control joint sealant where it does not match brick.
- 8. Apply sealant to joints in all cast stone sills and caps rather than mortar.

## Specific:

- 1. Replant/replace trees and shrubs that are not planted per the details on the Drawings.
- 2. Repair/replace concrete at threshold where broken at main entry doors.
- 3. Repair/replace chipped cast stone sign cap.
- 4. Paint steel columns and rainwater leaders.
- 5. Pick rocks from all yard areas.
- 6. Repaint asphalt striping.
- 7. Fill soil to elevation of sidewalks.
- 8. Install metal siding panels.
- 9. Caulk all sidewalk joints.
- 10. Caulk all joints where concrete pavement abuts brick.
- 11. Caulk all joints in cast stone window sills.
- 12. Correct sloping canopy soffits where they meet aluminum storefronts.
- 13. Remove rust from door A151 area.
- 14. Clean concrete splatter from brick at door A151 area.
- 15. Repair/Replace cracked cast stone window sill at Room 112.
- 16. Repair corner of right hand window at Room 113.
- 17. Apply sealant in control joint at right hand window Room 114.
- 18. Rub and fill concrete sills at Room 116.
- 19. Repair head flashing at left hand window of Room 116.
- 20. Install sunshades.
- 21. Finish sealant at wall control joint left side of Room 116 frame.
- 22. Replace damaged aluminum window frame at left hand window Room 116.
- 23. Remove string from right hand window Room 117.
- 24. Reset cast stone sill at left hand window at Room 117.

Exterior Punch List Chapmanville Intermediate School Page 2

- 25. Repair/Replace cast stone sill at Room 119.
- 26. Caulk around pipe.
- 27. Caulk joints in concrete pavement.
- 28. Repair/Replace broken brick corner at Stair B.
- 29. Remove nails at Door BIII.
- 30. Repaint door edge at Door BIII.
- 31. Repair/Replace acid stained door hardware at Door B111.
- 32. Clean soffit at Door BIII.
- 33. Replace brick and mortar at right hand window at Room 122.
- 34. Repair/Replace chipped cast stone sill.
- 35. Repair metal base flashing at right hand window at Room 123.
- 36. Remove construction material from roof of mechanical room.
- 37. Repair brick and mortar at corner of mechanical room.
- 38. Replace ill-fitting cast stone sills at kitchen windows.
- 39. Clean and paint bollards.
- 40. Clean and paint Door A146 and frame.
- 41. Replace dead shrub.
- 42. Repair/replace chipped brick at vent at Gym near Door A146.
- 43. Clean brick columns at Door A146.
- 44. Cut away insulation at drain pipe at column at Door A146.
- 45. Repair broken concrete at corner of column.
- 46. Relocate rainwater drain to align with downspout and install with boot.
- 47. Phase 5 roof, remove glue from brick.
- 48. Phase 5 roof, repoint wrong color mortar.
- 49. Phase 5 roof, install handrail and safety post on roof hatch.
- 50. Phase 3 and 4 roofs, install clamps on all gas lines.
- 51. Phase 4 roof, remove ladder.
- 52. Phase 3 roof, install handrail and safety post on roof hatch.

COI	S OWNER	H CONTRACTOR	ARCHITECT	Date of Punch	CHAPMANVILLE INTERMEDIATE SCHOOL INTERIOR - Ist FLOOR PUNCH LIST
					Punch List Information:
					The purpose of this meeting was to observe work in place and work incomplete and to generate a punch list of items needing attention of the contractor.
					Future punch lists will be provided by Harper Engineering and Terradon Corporation for the MEP and Site work respectively.
					Contractors are responsible for obtaining a Certificate of Occupancy from the West Virginia State Fire Marshals' office and submitting all closeout documents.
					Prior to release of Final Payment to the contractor(s), all punch lists items must be completed and reported as such by Contractors and approved by owner, architect and School Building Authority of West Virginia.
					General
1					Contractor is to submit all close out documents per Spec Section 017700 and SBA FORM 178.
2					Install lock cylinders
3					Adjust fit and hardware on all casework doors
4					Repair gypum drywall as marked
5					Remove protective coverings from kick plates and hardware
6					Final clean all surfaces
7					Straighten all devices to be plumb
8					Replace all ceiling tile as marked
9					Repair / Replace all floor tile as marked
10					Apply sealant at all window sills
11					Check all computer charging stations for proper operation

12	Apply small bead of sealant where ceiling grid wall angles meet wall.
13	Adjust all window shades for easier operation.
14	Straighten all rubber window gasketing.
15	Clean and buff all floor drain grates and cleanouts.
16	Confirm all room signs with the Door Schedule.
17	100 Vestibule
18	See General Items
19	Complete installation of display cases.
20	
21	101 General Office
22	See General Items
23	Caulk around countertops.
24	Paint metal door frame and structural steel.
25	Caulk around aluminum framing.
26	Touch up paint on bulkhead.
27	Finish aluminum frame work at Door A105.
28	Replace cracked vertical blind elements.
29	Apply sealant at bottom of Door Frame.
30	Properly install Rubber Base in corners.
31	Install door silencers on door frames
32	Door Frame not plumb / Needs to be adjusted
33	
	Williamson Chrivar Architects Inc

34	101a Reception
5	See General Items
6	
7	101b Man Trap
3	See General Items
)	Repair drywall at fire pull station.
0	Caulk aluminum frame.
1	Straighten ceiling.
2	
.3	101c Work Room
4	See General Items
.5	Support Rubber Base where marked.
.6	Repair plastic laminate on end of mailbox unit and shelving unit.
7	Replace incorrect ceiling tile.
8	Install correct room sign.
.9	
0	102 Assistant Principal
1	See General Items
52	Install correct room sign.
53	
4	103 Conference
55	See General Items

56	Door Frame not plumb / Needs to be adjusted
57	Touch up paint.
58	Remove protective covering from whiteboard.
59	Replace floor tile at door frame to eliminate gaps.
60	
61	104 Principal
62	See General Items
63	Install correct room sign.
64	Properly install Rubber Base in corners.
65	Adjust ceiling tile above door,
66	Repair/replace dirty or chipped light fixture.
67	
68	105a Toilet
69	See General Items
70	
71	105b Toilet
72	See General Items
73	Replace ceramic tile behind toilet.
74	
75	106 Guidance
76	See General Items
77	Install door strike.
—	 Williamson Chriver Architects Inc

78		Install door.
79	П	Properly install Rubber Base in corners.
80		Support Rubber Base where marked.
81		Door Frame not plumb / Needs to be adjusted
82		
83		107 Records
84		See General Items
85		Door Frame not plumb / Needs to be adjusted
86		
87		108 Clinic
88		See General Items
89		Support Rubber Base where marked.
90		Add filler panel next to refridgerator.
91		Level refridgerator.
92		Add all screws to metal window frame.
93		Repair bulge in drywall below window.
94		Install door silencer on correct side of frame.
95		Caulk and paint aroun window frame.
96		Caulk sink.
97		Straighten ICF wall.
98		Replace ceiling grid as required.
99		

100	100e Teilet
100	108a Toilet
101	See General Items
102	Replace ceramic tile where marked.
103	Replace sharp edged ile in shower.
104	Remove ceiling grid and replace with single wall angle.
105	Correct uneven floor tile along fixture wall.
106	Apply sealant at bottom of Door Frame.
107	
108	109 Hall
109	See General Items
110	Properly install Rubber Base in corners.
111	Touch up wall paint.
112	Correct wall base.
113	Touch up door frame paint.
114	
115	109a Hall
116	See General Items
117	
118	110 Storage
119	See General Items
120	Properly install Rubber Base in corners.
121	Finish installing shelving.
	Williamson Shrivar Architects Inc

2	
3	111 Stair "A"
	See General Items
5	Adjust top door strike.
6	Repair bent door frame.
7	Repair hump in wall.
8	Caulk around all steel.
.9	Paint door frame.
30	Add corner guard to wall under stairs.
31	Caulk around door frame.
32	Clean unit heater.
33	Apply sealant at bottom of Door Frame.
34	Repaint all steel railings
35	Grind all welds smooth.
36	Repair dented window frame.
37	Clean window frame.
38	Remove black sealant from outside window.
39	
40	112 Classroom
41	See General Items
12	Apply sealant at bottom of Door Frame.
43	Door Frame not plumb / Needs to be adjusted
	Williamson Shriver Architects Inc

144	Adjust Hardware on Door.
145	Repair/Replace chipped bookshelves.
146	Replace bowed table.
147	Repair bowed wall above door.
148	Remove and repair drywall screw above window.
149	Clean paint from ceiling grid.
150	Repair/ replace warped speaker.
151	
152	113 Classroom
153	See General Items
154	Door Frame not plumb / Needs to be adjusted
155	Properly install Rubber Base in corners.
156	Adjust Hardware on Door.
157	Adjust Light Fixtures to be Level.
158	Repair dented door frame.
159	Adjust/straighten window shade.
160	Clean paint from marble sill.
161	Clean paint from base.
162	Clean glue from desk.
163	
164	114 Speech
165	See General Items
	Williamson Chrivar Architects Inc

166	Clean or replace return air grill.
167	Install missing door hardware.
168	Door Frame not plumb / Needs to be adjusted
169	Apply sealant at bottom of Door Frame.
170	Adjust Hardware on Door.
171	Properly install Rubber Base in corners.
172	Support Rubber Base where marked.
173	Install hardware on computer charging station.
174	Install base on computer charging station.
175	Clean stickers from windows.
176	
177	115 Work Room
178	See General Items
179	Apply sealant at bottom of Door Frame.
180	Adjust Hardware on Door.
181	Properly install Rubber Base in corners.
182	Repair hole on wall cabinet.
183	Clean ceiling diffuser.
184	Clean ceiling grid.
185	Finish installing hardware on refrigerator.
186	
187	115a Toilet
	Williamson Shrivar Architects Inc

188	See General Items
189	Diagnose and eliminate noise in bathroom ceiling in fan or ductwork.
190	Clean dirty tile.
191	Square up chase wall.
192	
193	116 Classroom (Special Education)
194	See General Items
195	Support Rubber Base where marked.
196	Door Frame not plumb / Needs to be adjusted
197	Adjust Light Fixtures to be Level.
198	Finish dryer install.
199	Replace damaged ceiling grid.
200	Clean paint from base.
201	Repair base.
202	Caulk window.
203	Touch up window frame.
204	
205	116a Storage
206	See General Items
207	Support Rubber Base where marked.
208	Door Frame not plumb / Needs to be adjusted
209	Install door silencers on door frames
	Williamson Shrivar Architects Inc

210	Reinstall crooked shelving.
211	Install missing ceiling tile.
212	
213	116b Toilet
214	See General Items
215	Grout base at floor.
216	Caulk base in shower.
217	Realign crooked base in shower.
218	Install missing ceiling tile.
219	Install door silencers on door frames
220	Verify acceptable drainage in shower with threshold.
221	
222	117 Classroom
223	See General Items
224	Repair door frame which is bent at bottom.
225	Clean ceiling grid.
226	Replace bent ceiling grid.
227	Repair wall where drywall is not behind frame.
228	Apply sealant at bottom of Door Frame.
229	Adjust Hardware on Door.
230	Adjust Light Fixtures to be Level.
231	Properly install Rubber Base in corners.
	Williamson Chriver Architects Inc

232	Support Rubber Base where marked.
233	Door Frame not plumb / Needs to be adjusted
234	
235	118 Classroom
236	See General Items
237	Door Frame not plumb / Needs to be adjusted
238	Adjust Hardware on Door.
239	Repair drywall that is flush with window frame.
240	Remove white tile.
241	Clean ceiling grid.
242	Repair/replace speaker not flush.
243	Support Rubber Base where marked.
244	Apply sealant at bottom of Door Frame.
245	Properly install Rubber Base in corners.
246	Adjust Light Fixtures to be Level.
247	
248	119 Classroom
249	See General Items
250	Replace bent ceiling tiles.
251	Repair/replace damaged chair.
252	Door Frame not plumb / Needs to be adjusted
253	Apply sealant at bottom of Door Frame.
	Williamson Shriver Architects Inc

254	Adjust Hardware on Door.
255	Properly install Rubber Base in corners.
256	Adjust Light Fixtures to be Level.
257	
258	120 Stair "B"
259	See General Items
260	Adjust doors - Hitting at top corners and one door hinge is sprung.
261	Grind all welds and repaint
262	121 Classroom (Title 1)
263	See General Items
264	Apply sealant at bottom of Door Frame.
265	Adjust Hardware on Door.
266	Door Frame not plumb / Needs to be adjusted
267	Properly install Rubber Base in corners.
268	
269	122 Classroom
270	See General Items
271	Realign ceiling grid to be flush with wall.
272	Repalce chair with rusted legs.
273	Replace bent ceiling grid.
274	Clean base.
275	Adjust Light Fixtures to be Level.
	Williamson Chrivar Architects Inc.

276	Properly install Rubber Base in corners.
277	Adjust Hardware on Door.
278	Apply sealant at bottom of Door Frame.
279	Support Rubber Base where marked.
280	
281	Corridor between Stair 'A' 111 and Lobby C01
282	See General Items
283	Straighten ICF wall.
284	Replace bent ceiling grid.
285	Touch up wall paint.
286	Adjust Door A119 on Storage Room 110
287	
288	123 Classroom
289	See General Items
290	Door Frame not plumb / Needs to be adjusted
291	Apply sealant at bottom of Door Frame.
292	Adjust Hardware on Door.
293	Properly install Rubber Base in corners.
294	Adjust Light Fixtures to be Level.
295	Clip wire on light fixture.
296	Repair window sill.
297	Touch up paint on door frame.
	Williamson Chrivar Architects Inc

298	Remove casework shim.
299	
300	124 Classroom (OT/PT)
301	See General Items
302	Repair bent door frame.
303	Install one piece ceiling grid wall angle over door.
304	Check label on door frame.
305	Properly install Rubber Base in corners.
306	Door Frame not plumb / Needs to be adjusted
307	Adjust Hardware on Door.
308	Apply sealant at bottom of Door Frame.
309	
310	124a Storage
311	See General Items
312	Change door swing to comply with Drawings.
313	Properly install Rubber Base in corners.
314	
315	125 Custodian
316	See General Items
317	Apply sealant at bottom of Door Frame.
318	
319	126 Network
	Williamson Shrivar Architects Inc.

320	See General Items
321	
322	127 Electrical
323	See General Items
324	
325	128 Classroom
326	See General Items
327	Repair dent in door frame and repaint.
328	Install casework shelving.
329	Repair inoperable light fixture.
330	Repair warped door.
331	Door Frame not plumb / Needs to be adjusted
332	Support Rubber Base where marked.
333	Apply sealant at bottom of Door Frame.
334	Adjust Hardware on Door.
335	Properly install Rubber Base in corners.
336	Adjust Light Fixtures to be Level.
337	
338	129 Classroom
339	See General Items
340	Repair/replace chipped door.
341	Repair door frame and repaint.
	Williamson Shrivar Architects Inc.

342	Replace bent ceiling grid.
343	Install casework shelving.
344	Replace outlet cover.
345	Touch up paint above door frame.
346	Realign ceiling grid to be flush with wall.
347	Reset drain.
348	Properly install Rubber Base in corners.
349	Door Frame not plumb / Needs to be adjusted
350	Support Rubber Base where marked.
351	Apply sealant at bottom of Door Frame.
352	Adjust Hardware on Door.
353	Adjust Light Fixtures to be Level.
354	
355	130 Mechanical
356	See General Items
357	Repair exterior door threshold to comply with Detail A on Drawing A-101.
358	Clean floor and piping.
359	Paint all gas piping yellow.
360	Paint hollow metal door frames.
361	Provide proper air gap for 2 inch copper condensate drain.
362	Remove all overstock materials and tools.
363	
	Williamson Chrivar Architects Inc

	131 Electrical
	See General Items
++-	Joee General Items
	Finish door closer install.
	Apply final coat of paint incuding conduit.
	Remove overstock light fixtures, tools, etc.
	Adjust exterior door operation.
	Repair exterior door threshold to comply with Detail A on Drawing A-101.
	Clean floor.
	132 Custodian Office
	See General Items
	Paint hollow metal door frames.
	Install flooring.
	Remove debris.
	132a Toilet
	See General Items
	Install handrail with blocking.
	Paint hollow metal door frame.
	133 Elevator Equipment Room
++-	See General Items
	See General Items  Paint hollow metal door frames.  Install flooring.  Remove debris.  132a Toilet  See General Items  Install handrail with blocking.  Paint hollow metal door frame.  133 Elevator Equipment Room

386	Provide correct room sign.
387	Fireseal 2 inch copper pipe.
388	Clean floor.
389	Remove bracket on right hand wall, repair drywall and paint.
390	Paint hollow metal door frames.
391	
392	134 Elevator
393	See General Items
394	Clean all doors.
395	Caulk all floor tile.
396	
397	135a Boys
398	See General Items
399	Repair sharp tile edges.
400	Repair sharp edge between urinals.
401	Install overhead brace on stall.
402	Touch up all grout.
403	Repair bowed wall tile behind sinks.
404	Replace missing screw on stall.
405	Repair/replace holes in toilet partitions.
406	Straighten misaligned toilet partitions.
407	
	Williamson Shrivar Architects Inc

1 1 1	
108	135b Girls
09	See General Items
.0	Repair sharp tile edges.
.1	Realign toilet partitions.
2	Touch up all grout.
3	Clean grout from tile.
.4	
15	136 Network
16	See General Items
17	Door Frame not plumb / Needs to be adjusted
18	Install base.
19	Remove spilled concrete.
20	
21	137 Custodian
22	See General Items
23	
24	138 Food Prep
25	See General Items
26	At Door A144, paint frame and door.
27	Clean cooler/freezer walls inside and outside.
28	Clean all FRP wall panels.
29	Caulk under fire alarm strobe.
	Williamson Chrivar Architects Inc

430	Paint all door frames.
431	Finish ceiling install.
432	Install icemaker.
433	Clean PVC cleanout on wall.
434	Patch holes in FRP at gas line support.
435	Install hose reel near laundry.
436	Clean floors.
437	Patch holes in resinous floor under warmer and cooler cabinets.
438	Remove dents in warmer cabinet.
439	Replace escutcheon on hand sink drain with proper size.
440	Provide locker number plates on lockers (number 1 through 4).
441	
442	138a Serving
443	See General Items
444	
445	138b Dish Wash
446	See General Items
447	Clean all FRP wall panels.
448	Clean floor and base below table.
449	Adjust water flow at disposer.
450	Clean Steve's chalk errant marks from ceiling tile.
451	Remove plastic protection from coiling door.
	Williamson Chrivar Architects Inc

<del>                                      </del>	<u> </u>
452	
453	138c Non Food Storage
454	See General Items
455	
456	138d Laundry
457	See General Items
458	
459	138e Toilet
460	See General Items
461	Install door silencers on door frames
462	Door Frame not plumb / Needs to be adjusted
463	Clean floor tile grout.
464	Finish ceiling install.
465	Caulk ceramic base at left door jamb.
466	Paint hollow metal door frame.
467	Install larger flush valve escutcheon
468	
469	138f Freezer
470	See General Items
471	
472	138g Cooler
473	See General Items
	Williamson Shriver Architects Inc

474	
475	138h Dry Food Storage
476	See General Items
477	Adjust Hardware on Door.
478	Clean or replace discolored or dirty FRP wall panels.
479	Repaint hollow metal door frame.
480	Install light switch cover.
481	
482	138j Office
483	See General Items
484	Properly install Rubber Base in corners.
485	Apply sealant at bottom of Door Frame.
486	Install door silencers on door frames
487	Clean floor.
488	Install all screws in window frame.
489	Repair and repaint hollow metal frames.
490	Locate keys to desk.
491	
492	139 Gymnasium
493	See General Items
494	Repair and repaint IFA frame at Doors A147 and A146.
495	Install controls for basketball rim adustment mechanism.
	Williamson Shriyar Architects Inc

496	Clean wall pads.
497	Provide weatherstripping on center mullion at Doors A147 and A146.
498	Repaint top portion of transfer duct grill to match wall.
499	Paint stainless steel cover plate above Door A146 to match wall.
500	
501	139a Gymnasium Storage
502	See General Items
503	Install flooring.
504	Repair finish on doors.
505	Adjust HVAC unit to be level.
506	Repair floor slab at doors.
507	Apply sealant at bottom of Door Frame.
508	Adjust Hardware on Door.
509	Properly install Rubber Base in corners.
510	
511	140 Dining
512	See General Items
513	Apply sealant at bottom of Door Frames.
514	Repair and repaint all IFA frames.
515	Replace bubble glass in Door A148.
516	Touch up paint on large operable partition.
517	Repair sharp screws on large operable partition.
	Williamson Chrivar Architects Inc

518	Clean all scuff on large operable partition.
519	Patch drywall in large operable partition bulkhead.
520	Instal access panel in large operable partiton bulkhead.
521	Realign jamb trim on large operable partition to be plumb.
522	Remove welded stubs on all IFA frames, repair, and repaint.
523	Repair floor tile at Door A138.
524	Remove overspray from projection screen.
525	Stage edge black rubber treads need to be repaired/realigned. Clean and caulk gaps with black sealant. Provide additional adhesive to secure front edges.
526	
527	141 Ramp
528	See General Items
529	Properly install Rubber Base in corners.
530	Repar top and side of hollow metal door frame.
531	Repair scratch on outside of door.
532	Door A149 lacks proper ADA clearance as designed. Need to correct.
533	
534	142 Music
535	See General Items
536	Repaint all walls.
537	Touch up and clean at operable partition recess.
538	Clean operable partition.

Touch up bulkhead at operable partition.
Adjust ceiling tile at sprinkler head at stage left.
142a Storage
See General Items
CO1 Lobby
See General Items
C02 Corridor
See General Items
Feather floor tile outside gang toilets.
CO2a Corridor
See General Items
Adjust Hardware on Door.
Properly install Rubber Base in corners.
Clean fire extinguisher cabinet.
C02b Corridor
See General Items
Repair and repaint IFA frame.

561			Door A152 lacks magnetic hold-open extension.
562			Clean and touch up coiling door.
563			Clean stainless steel.
564			
565			CO3 Corridor
566			See General Items
567			Door A152 lacks magnetic hold-open extension.

CO	전 OWNER	T CONTRACTOR	ARCHITECT	Date of Punch	CHAPMANVILLE INTERMEDIATE SCHOOL INTERIOR - SECOND FLOOR PUNCH LIST
					Punch List Information:
					The purpose of this meeting was to observe work in place and work incomplete and to generate a punch list of items needing attention of the contractor.
					Additional punch lists will be provided by Harper Engineering and Terradon Corporation for the MEP and Site work respectively.
					Contractors are responsible for obtaining a Certificate of Occupancy from the West Virginia State Fire Marshals' office and submitting all closeout documents.
					Prior to release of Final Payment to the contractor(s), all punch lists items must be completed and reported as such by Contractors and approved by Owner, Architect and School Building Authority of West Virginia.
					General
1					Contractor is to submit all close out documents per Spec Section 017700 and SBA FORM 178.
2					Install lock cylinders
3					Adjust fit and hardware on all casework doors
4					Repair gypum drywall as marked
5					Remove protective coverings from kick plates and hardware
6					Final clean all surfaces
7					Straighten all devices to be plumb
8					Replace all ceiling tile as marked
9					Repair / Replace all floor tile as marked
10					Apply sealant at all window sills
11					Check all computer charging stations for proper operation

		_
12		Apply small bead of sealant where ceiling grid wall angles meet wall.
13		Adjust all window shades for easier operation.
14		Straighten all rubber window gasketing.
15		Clean and buff all floor drain grates and cleanouts.
16		Confirm all room signs with the Door Schedule.
17		200 Stair "A"
18		Refer to 111 Stair "A" Punch List Items
19		
20		201 Classroom
21		See General Items
22		Door Frame not plumb / Needs to be adjusted
23		Support Rubber Base where marked.
24		Apply sealant at bottom of Door Frame.
25		Repair Drywall where marked.
26		Properly install Rubber Base in corners.
27		Recut in all corners with paint.
28		Adjust Light Fixtures to be Level.
29		Repair chip on tall cabinet door.
30		Clean paint from wiremold.
31		Clean sawdust from computer cabinet.
32		Clean paint from base.
33		Repair scratch on student desk top.
	<u> </u>	Williamson Chrivar Architects Inc

34	
35	202 Classroom
36	See General Items
37	Door Frame not plumb / Needs to be adjusted
38	Apply sealant at bottom of Door Frame.
39	Adjust Hardware on Door.
40	Properly install Rubber Base in corners.
41	Tall cabinet door warped.
42	Replace Light fixture bulb.
43	Adjust Light Fixtures to be Level.
44	Clean paint from base.
45	Repair chipped bookshelf.
46	
47	203 Classroom (Gifted)
48	See General Items
49	Door Frame not plumb / Needs to be adjusted
50	Apply sealant at bottom of Door Frame.
51	Adjust Hardware on Door.
52	Properly install Rubber Base in corners.
53	Adjust Light Fixtures to be Level.
54	Fix sealant in corner of window.
55	

	204 Work Room
	See General Items
	Finish drywall work behind refridgerator.
	Remove paint from base.
	Door Frame not plumb / Needs to be adjusted
	Adjust Hardware on Door.
	Properly install Rubber Base in corners.
	Adjust Light Fixtures to be Level.
	Apply sealant at bottom of Door Frame.
	204a Toilet
	See General Items
	Repair tile and grout.
	Paint door frame.
	Repair bent Grill.
	Apply sealant at bottom of Door Frame.
	Door Frame not plumb / Needs to be adjusted
	Support Rubber Base where marked.
_	205 former STEM Lab
	See General Items

78	Clean paint from base.
79	Replace bent ceiling grid.
80	Remove tape from tile frame.
81	Adjust Hardware on Door.
82	Door Frame not plumb / Needs to be adjusted
83	Adjust Light Fixtures to be Level.
84	Support Rubber Base where marked.
85	Properly install Rubber Base in corners.
86	Apply sealant at bottom of Door Frame.
87	
88	206 Classroom
89	See General Items
90	Repair inoperable Light fixture.
91	Door Frame not plumb / Needs to be adjusted
92	Support Rubber Base where marked.
93	Adjust Light Fixtures to be Level.
94	Properly install Rubber Base in corners.
95	Apply sealant at bottom of Door Frame.
96	
97	207 Classroom
98	See General Items
99	Door Frame not plumb / Needs to be adjusted
	Williamson Chriver Architects Inc

100	Properly install Rubber Base in corners.
101	Adjust Light Fixtures to be Level.
102	Apply sealant at bottom of Door Frame.
103	
104	208 Classroom
105	See General Items
106	Repair inoperable light fixture.
107	Install receptacle cover.
108	Remove casework shims.
109	Repair floor where marked along base.
110	Clean paint from ceiling trim.
111	Adjust Hardware on Door.
112	Support Rubber Base where marked.
113	Apply sealant at bottom of Door Frame.
114	Adjust Light Fixtures to be Level.
115	
116	209 Stair "B"
117	Refer to 120 Stair "B" Punch List Items
118	
119	210 Classroom (Title 1)
120	See General Items
121	Clean wall under return.
	Williamson Shriver Architects Inc

122	Repair or replace cracked door.
123	Properly install Rubber Base in corners.
124	Adjust Hardware on Door.
125	Apply sealant at bottom of Door Frame.
126	
127	211 Classroom
128	See General Items
129	Adjust ball chain guide on both window shades.
130	Repair possible water leak in window.
131	Clean white residue from casework.
132	Repair window sealant.
133	Adjust Hardware on Door.
134	Door Frame not plumb / Needs to be adjusted
135	Support Rubber Base where marked.
136	Adjust Light Fixtures to be Level.
137	Apply sealant at bottom of Door Frame.
138	
139	212 Classroom
140	See General Items
141	Adjust window shade.
142	Repair window frame.
143	Replace bent ceiling grid.
	 Williamson Chrivar Architects Inc

144	Repair holes in door frame.
145	Adjust Light Fixtures to be Level.
146	Apply sealant at bottom of Door Frame.
147	Door Frame not plumb / Needs to be adjusted
148	Properly install Rubber Base in corners.
149	
150	213 Classroom (Title 1)
151	See General Items
152	Install shelving.
153	Door Frame not plumb / Needs to be adjusted
154	Apply sealant at bottom of Door Frame.
155	Properly install Rubber Base in corners.
156	
157	214 Custodian
158	See General Items
159	Adjust Hardware on Door.
160	
161	215 Network
162	See General Items
163	Firestop all wall penetrations
164	Adjust Hardware on Door.
165	Door Frame not plumb / Needs to be adjusted
	 Williamson Chrivar Architects Inc

166	
167	216 Electrical
168	See General Items
169	Seal wall below steel beam.
170	Caulk around light switch.
171	Repair/Firestop floor and wall penetrations.
172	Door Frame not plumb / Needs to be adjusted
173	Adjust Hardware on Door.
174	
175	217 Classroom
176	See General Items
177	Repair window frame.
178	Straighten window shades.
179	Repair window sealant.
180	Properly install Rubber Base in corners.
181	Adjust Light Fixtures to be Level.
182	Apply sealant at bottom of Door Frame.
183	
184	218 Classroom
185	See General Items
186	Repair dented window frame.
187	Repair window shade bracket.
	Williamson Chriver Architects Inc

188	Correct casework trim against window frame.
189	Repair cracked door.
190	Apply sealant at bottom of Door Frame.
191	Support Rubber Base where marked.
192	
193	219 Classroom (Spec. Ed. Sm. Gr.)
194	See General Items
195	Repair window shade bracket
196	Caulk drywall on angle on outside window.
197	Remove shim above computer cabinet.
198	Paint around door frame.
199	Replace door sign with specified label.
200	Door Frame not plumb / Needs to be adjusted
201	Properly install Rubber Base in corners.
202	
203	219a Storage
204	See General Items
205	Install door silencers on door frames
206	Adjust Hardware on Door.
207	
208	220 Elevator
209	See General Items
	Williamson Chriver Architects Inc

210	Clean frame.
211	
212	221a Boys
213	See General Items
214	Anchor toilet partitions.
215	Smooth edges of toilet partitions.
216	Touch up grout on all tile areas.
217	Adjust sensor on urinal.
218	Address uneven wall.
219	Patch drywall around sprinkler head.
220	Smooth and touch up corners of bulkhead.
221	Remove marks on tile.
222	Install overhead brace on stall.
223	
224	221b Girls
225	See General Items
226	Adjust first stall toilet partition to be square to wall.
227	Adjust toilet partitions to proper alignment.
228	Replace protruding ceramic wall tile.
229	Touch up al tile grout.
230	Apply sealant at hand sinks.
231	Correct sharp cut wall tile at wall jambs.
	Williamson Shriver Architects Inc

232	Tile/bulkhead/wall intersection needs to be fixed.	
233		
234	222 Storage	
235	See General Items	
236		
237	222a Network	
238	See General Items	
239	Install access doors.	
240	Install proper firesafing.	
241	Clean floors.	
242		
243	CO4 Corridor	
244	See General Items	
245	Support Rubber Base where marked.	
246	Properly install Rubber Base in corners.	
247	Repair dented door frame.	
248	Install tile and base.	
249	Adjust door to prevent hitting landing framing.	
250	Install door hardware on stair doors.	
251	Adust locker doors as required.	
252	Repair replace fabric covered acoustical panels.	
253	Reinstall floor tile to eliminate gaps at door frames.	
	Williamson Chrivar Architacts Inc	

254	Replace door signs with specified labels.
255	Adjust/repair locker numbers 76, 78, 80, 110, 156, 175, 185, 193, 195, 201, and 207.
256	Shim lockers to provide correct alignment along wood trim.
257	Clean ceiling diffuser.
258	Adjust door hardware at door where pin is dragging the floor.
259	Paint, Repaint, touch up stair framing and railings.
260	Add floor stops to stair doors.
261	Caulk window frame.
262	Replace tile to eliminate gaps to steel.
263	Feather floor tile outside gang toilets.
264	Straighten bowed wall at west end across from Stair 'B'. (item added 2018 08 27)